

## SUBJECT: TIME TO SEVICE INCREASED TO 50 HOURS

Engine type:	H16
Serial numbers:	007 and up
Compulsory:	NO
Due date:	-

Safety urgency:

High	
Medium	
Low	
N/A	X

Reason:

Time to engine servicing is increased from 30 hours to 30h.

Live limited parts replacement intervals has been increased to reflect this change accordingly:

Part	life [hours]
Rotor bearings	50
Turbine wheel	200
Compressor wheel	100
Kevlar containment ring	100

This change is reflected in the User manual from revision 16.

Action:

NIL

Issued: 28th Feb 2016